

CONTROL

FOR THE PROCESS INDUSTRIES

FULL THROTTLE BATCH AND STARTUP RESPONSE

Improvements in practices for starting up a loop with a large process time constant or slow ramp time compared to the dead time can save 25% or more in batch cycle and startup time. **by Gregory K. McMillan, Control columnist**

The time it takes to bring a slow process variable from its minimum or maximum to set point can be a significant portion of a batch or startup phase. The more important analytical loops, pressure, and temperature loops often have a response that ramps most of the way to set point.

In batch processes, the ramp is most likely due to the process actually having an integrating response because the discharge valve and possibly the vent valve are closed at the start of the batch. The outlet valves also may be closed in continuous processes when a vessel is being filled or pressurized.

Even when the startup of a continuous loop is delayed until after an outlet flow is established, the small dead time and large time constant of a well-mixed volume results in a loop response that looks like an integrator. Even more problematic is the runaway response, where the process variable actually starts to accelerate. All of these responses benefit from special considerations, such as using a Lambda factor of less than 1.0 and pre-positioning valves, as discussed in "Life is a Batch," *Control*, June '05, p. 80, and in a dozen "Control Talk" columns on process control techniques and tuning for batch processes.

Most of the articles and books on tuning loops concentrate on set point and load changes around operating point. For integrating processes, the focus is on surge tank level

loops because these are the major source of variability in a plant because they jerk feeds around or cause a rolling action primarily from too much reset action (too little reset time). Bringing a composition, pressure, or temperature rapidly from either end of the scale to a set point is a different story.

Nothing Says Forever Like Tradition

There are four major practices for starting up a loop with a large process time constant or slow ramp time compared to the dead time. These loop practices for fast batch and startup response are:

- 1) Switch controller to auto with the final set point
- 2) Switch controller to auto with an initial set point, and then switch to final set point
- 3) Put controller in manual or output tracking with final set point, set valve to its normal position, wait, and switch to auto
- 4) Put controller in manual or output tracking with final set point, set valve to extreme position, wait, switch valve to normal position, wait, and switch to auto


Figure 1 shows the batch or startup response of a pressure loop with an integrating response for practices 1, 2, and 4. Practice 3 isn't shown because it's not viable for integrating processes. There are other practices, such as ramping the set point, for unit operations, where it's desirable that the approach of the process variable to set point and the output to its final resting value is moderated or that a profile be enforced.

In practices 1 and 2, the controller output is at its initial value at one end or the other of the output scale (often zero). All methods assume the pump and block valves have already been started and opened, respectively.

In Practice 1, if the loop is tuned to minimize variability in the controller output, which is the case for surge-volume level control, the batch phase may time out before the process reaches set point. For example, if the process time constant is 50 min, and a Lambda factor of 5 is used, then the closed-loop time constant is 250 min, and the time to reach 98% of set point is 1,000 min (or four closed-loop time constants). A similar situation exists for slow ramp rates. For integrating processes, the Lambda factor is the ratio of the closed-loop arrest time to the open-loop arrest time. The arrest time is the time it takes for a PV to make a designated allowable excursion for a given upset.

FIGURE 1.

BATCH AND STARTUP



This graph shows the batch or startup response of a pressure loop with an integrating response for practices 1, 2, and 4.

FULL THROTTLE

In Practice 2, the set point is changed from its initial to final value at one execution or more after the controller is switched to auto. Note that, if you switch the set point within the same execution of the module as the switch of the mode, then you'll probably end up with the same response as Practice 1. In the second batch or startup response, the set point change kicks the output, which gives the process variable a boost on its way to set point. The time to reach set point (rise time) is nearly cut in half, but the settling time is about the same. Since the overshoot is minimal, the rise time might be more important. Also, the controller tuning could be tweaked to reduce settling time.

Many astute automation engineers will reposition the controller output by what is called a "head start" or "process action." For self-regulating loops, the valve position might set at what was considered to be a normal throttle position or final resting value (FRV) seen from previous trends when the process variable had settled out at set point. This corresponds to a Lambda factor of 1 because, if held at this position, it will drive the process variable with a time constant equal to the process time constant.

For integrating and runaway responses, the process variable won't go anywhere until the valve is positioned beyond its FRV. This leads to Practice 4, in which the valve is set to an extreme position allowed by the process to give the fastest approach to set point. Next, the brakes are slammed on, so the process variable doesn't run over the set point. It's kind of like driving in Italy. The question is when do you hit those brakes?

The Wait

Short of having an Italian taxi driver operate your loop, what can be done to get the loop to its destination in the fastest way possible?

The plot for Practice 4 shows the response for a technique briefly described in "Peak Concerns," Control Talk, *Control*, April '05, p. 75. The rate of change is computed from the change in the process variable (PV) over a time large enough to get a good signal-to-noise ratio. The old value of the PV, created by passing the PV through a dead time block, is subtracted from the new PV. The Δ PV is divided by the block dead time to create a rate of change. The rate of change multiplied by the process dead time is then the predicted change in the PV that, when added to the new PV, is the predicted end point shown in Equation 1. When the end point equals or exceeds the final set point, the controller output is switched from maximum throttle to its FRV. It's held at this FRV for one process dead time, and is then released for feedback control. This method compensates for nonlinearities and disturbances that are evident when it's time to hit the brakes.

[Equation 1]

$$PV_f = [(PV_n - PV_o) / DT] * \tau_d + PV_n$$

Where:

PV_f = predicted PV one dead time into the future (%)

PV_n = new PV (%)

PV_o = old PV (output of dead time block) (%)

DT = DT block dead time (sec)

τ_d = total loop dead time (sec)

If the process dead time is underestimated, the loop will overshoot the set point. Therefore, it's important to be generous in the dead time estimate. It's especially important the dead time not be too short for zero-load integrating process (as described in the "Peak Concerns" column), where the FRV is zero and there's nothing to bring back the process variable to set point. Also, a safety margin should be added to the dead time estimate for runaway processes since the process is accelerating.

Rest in Peace

The integrating process gain can be used with the current ramp rate and the pre-positioned extreme controller output to estimate the FRV per Equation 2. Note that, if the extreme output (OUT_x) is less than the FRV, the signs of each expression are reversed to get a positive FRV. The calculation should be limited and filtered. For primary loops in a cascade control system, the extreme output must not exceed the set point limits of the secondary loop. It's necessary to keep the units of the process variable and output and the process integrating gain consistent. If the process integrating gain is in %/sec/%, the process variable and output must both be in %. For integrating processes and $OUT_x > FRV$:

[Equation 2]

$$FRV = OUT_x - [(PV_n - PV_o) / DT] / K_i$$

Where:

FRV = final resting value (%)

K_i = integrating process gain (%/sec/%)

OUT_x = output at extreme allowed by process (%)

PV_n = new PV (%)

PV_o = old PV (output of dead time block) (%)

DT = DT block dead time (sec)

Next Destination

The optimal switching technique based on the rate of change of the PV is ideally suited for an integrating or ramping process, but works well for self-regulating and runaway processes where the fastest possible approach to set point is desired. It also reduces the dependency on tuning since the controller only has to correct for errors in the dead time and the FRV. These and other process control techniques can save 25% in batch cycle and startup time and get you to the next destination faster, which might just be happy hour. 

Greg McMillan is an inductee of the Process Automation Hall of Fame and is retired from Monsanto. He is a prolific author on process automation. He can be reached at gkmcmi@austin.rr.com.

Reprinted with permission from Control Magazine, May 2006.
© PUTMAN. All Rights Reserved. On the Web at www.controlmag.com.